MATERIAL SAFETY DATA SHEET

MANUFACTURER:

ROCK PAINT DISTRIBUTING CORP. PO BOX 482, 365 SUNNYSIDE DR MILTON, WI 53563 PHONE #: 608-868-6873 EMERGENCY #: 608-868-5401

SECTION I: PRODUCT IDENTIFICATION

PRODUCT NAME(S): PRODUCT SIZES: HANDY ART® FABRIC PAINT 2, 4, 8, 16 oz

SECTION II: HAZARDOUS INGREDIENTS

NONE PER OSHA 29 CFR 1910.1200

MATERIAL HAS THE ART & CREATIVE MATERIAL INSTITUTE, INC.'S AP SEAL. AP APPROVED PRODUCTS ARE CERTIFIED IN A PROGRAM OF TOXICOLOGICAL EVALUATION BY A MEDICAL EXPERT TO CONTAIN NO MATERIAL IN SUFFICIENT QUANTITIES TO BE TOXIC OR INJURIOUS TO HUMANS OR TO CAUSE ACUTE OR CHRONIC HEALTH PROBLEMS. THESE PRODUCTS ARE CERTIFIED BY ACMI TO BE IN ACCORDANCE WITH ASTM D-4236.

SECTION III: PHYSICAL AND CHEMICAL CHARACTERISTICS

BOILING POINT:~212 FMELTING POINVAPOR PRESSURE:N/AEVAPORATIONSPECIFIC VAPOR DENSITY (AIR =1):N/ASPECIFIC GRASOLUBILITY IN WATER:DILUTABLEREACTIVITY INAPPEARANCE AND ODOR:SLIGHT AMMONIA ODOR OR NO ODOR PRESENT

MELTING POINT: N/A EVAPORATION RATE: SLOWER THAN WATER SPECIFIC GRAVITY (WATER =1): 1.08-1.20 REACTIVITY IN WATER: N/A

SECTION IV: FIRE AND EXPLOSION INFORMATION

FLASH POINT (METHOD):N/AAUTOIGNITION TEMPERATURE:N/AEXPLOSION LIMITS IN AIR (% BY VOLUME):N/AEXTINGUISHING MEDIA:FOAM-DRY CHEMICAL-CO2-WATER SPRAY OR FOGSPECIAL FIRE FIGHTING PROCEDURES:N/AUNUSUAL FIRE & EXPLOSION HAZARDS:N/A

SECTION V: PHYSICAL HAZARDS/REACTIVITY

HAZARDOUS POLYMERIZATION PRODUCTS:NONESTABILITY: STABLE CONDITIONS TO AVOID:NONEINCOMPATIBILITY (MATERIALS TO AVOID):NONEHAZARDOUS DECOMPOSITION PRODUCTS:THERMAL DECOMPOSITION IN THE PRESENCE OF AIR MAY YIELD
CARBON MONOXIDE AND/OR CARBON DIOXIDE AND TRACES OF MONOMER

SECTION VI: HEALTH HAZARD DATA

PERMISSIBLE EXPOSURE LEVEL: SEE SECTION II FOR COMPONENT PEL/TLV'S PRIMARY ROUTES OF ENTRY: EYE, SKIN, INGESTION EFFECTS & SYMPTOMS OF ACUTE EXPOSURE: NONE EXPECTED EFFECTS & SYMPTOMS OF CHRONIC EXPOSURE: NONE EXPECTED CARCINOGEN LISTING: NTP: NO IARC: NOOSHA: NO SEE SECTION II FOR COMPONENTS AFFECTED MEDICAL CONDITIONS USUALLY AGGRAVATED BY OVER EXPOSURE TO THIS PRODUCT: NOT KNOWN. FIRST AID MEASUREMENTS: FOR EYES: FLUSH WITH WATER FOR 15 MINUTES. CONTACT PHYSICIAN. FOR SKIN: WASH WITH SOAP AND WATER. CONTACT PHYSICIAN IF UNLIKELY IRRITATION OCCURS. FOR INGESTION: CONTACT PHYSICIAN.

PAGE 1

SECTION VII: SPILL OR LEAK PROCEDURES

PRECAUTIONS TO BE TAKEN DURING STORAGE AND HANDLING: STORE UNDER NORMAL ROOM CONDITIONS. STEPS TO BE TAKEN IN CASE A MATERIAL IS SPILLED: NO SPECIAL SPILL PROCEDURES REQUIRED. WASTE DISPOSAL METHOD: DISPOSE IN ACCORDANCE WITH FEDERAL, STATE AND LOCAL REGULATIONS.

SECTION VIII: PROTECTIVE EQUIPMENT/CONTROL MEASURES

RESPIRATORY PROTECTION & SPECIAL VENTILATION REQUIREMENTS: NONE REQUIRED UNDER NORMAL CONDITIONS OTHER PROTECTIVE EQUIPMENT (GLOVES, GOGGLES, ETC): NONE REQUIRED UNDER NORMAL CONDITIONS WORK/HYGIENE PRACTICES: NONE REQUIRED UNDER NORMAL CONDITIONS

SECTION IX: ADDITIONAL INFORMATION AND WARNINGS

NONE REQUIRED THIS INFORMATION IS FOR CONSUMER USE ONLY

SECTION X: COLOR INFORMATION

THIS MSDS APPLIES TO THE FOLLOWING COLORS WHICH ARE ASSOCIATED WITH HAZARDOUS AND/OR NON-HAZARDOUS

PRODUCT COLOR	HAZARDOUS INGREDIENT	PRODUCT COLOR HAZ	ARDOUS INGREDIENT
BASE	NONE	SKIPPER BLUE	NONE
BINDER	NONE	SPARKLE CANARY YELLOW	NONE
CANARY YELLOW	NONE	SPARKLE CARBON BLACK	NONE
CARBON BLACK	NONE	SPARKLE CHOCOLATE BROWN	NONE
CHOCOLATE BROWN	NONE	SPARKLE CHROME ORANGE	NONE
CHROME ORANGE	NONE	SPARKLE FLAG RED	NONE
FLAG RED	NONE	SPARKLE FOREST GREEN	NONE
FOREST GREEN	NONE	SPARKLE MIXING WHITE	NONE
FUCHSIA	NONE	SPARKLE PHTHALO BLUE	NONE
MIXING WHITE	NONE	SPARKLE VIOLET	NONE
PHTHALO BLUE	NONE	VIOLET	NONE
SCARLET	NONE		